

Product info sheet

Robert Bosch

0445116059

Special tools needed?

Yes

Use special tool to turn the coupling nut.



Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No


Bleed

Yes

ignition on for 30 seconds

adjustment at mounting_1

--



adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

1: 8 Nm, 2: 26 Nm

High Pressure pipe nuts

25 Nm

Assembly instructions

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

