

Product info sh	eet	Robert Bosch	0445124041
Special tools needed? Puller to remove inlet pipe	Yes		9998007
Product specific information			
Programming	No	•	
Unlocking	No		
Adaption values reset	No		
Bleed	No		
adjustment at mounting_1	No		
a diverter out at many mating.			
adjustment at mounting_2			
Tightening torques			
Bushing inlet pipe	ייפ	Step 1: 80 Nm	
Injector/ retainingclamp			
Straining screw inlet pipe			
Electrical connectors inject	cor	2 Nm	
High Pressure pipe nuts		1: 15 Nm 2: 45 Nm	
Assembly instructions			
Replace sealing washer		,	
Replace inlet pipe			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled,			
-no heavy corrosion.			