



# AUTOELECTRO

Since 1986

## STARTER MOTORS & ALTERNATORS

**IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY**

This unit is commonly returned for failure due to fluid contamination. Depending on the vehicle there are numerous sources of the fluid leak which can contaminate the unit.

It is critical that you visit our website to obtain information and carry out further investigations to locate the leak and rectify it prior to fitting the replacement unit. Failure to do so will cause the replacement unit to fail prematurely and will invalidate your warranty.

Look out for fluid residue, rust build up, distinctive smell and possible burning smell.

**FREE** vehicle specific technical information is available by visiting [autoelectro.co.uk](http://autoelectro.co.uk) OR scan this QR code



**The Original and Best**  
**Since 1986**