

## Product info sheet

Robert Bosch

0445110338

Special tools needed?

No

Injectors can be very stuck. Please contact us if you don't have the right equipment.

## Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting\_1

No

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

35 Nm

## Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

