

PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

PLEASE NOTE THIS PART NUMBERS HAS A VARIATION IN THE NUMBER OF GROOVES OF THE ALTERNATOR PULLEY.

THIS ALTERNATOR IS SUPPLIED WITH A PV4
PULLEY. IF YOUR OLD ALTERNATOR HAS A
PV3 PULLEY THIS MUST BE TRANSFERRED
TO THE NEW ALTERNATOR.

PLEASE ENSURE THE OLD UNIT IS INSPECTED AND THE ALTERNATOR YOU ARE FITTING HAS THE SAME NUMER OF GROOVES ON THE PULLEY PRIOR TO FITMENT.

FAILURE TO DO SO WILL REUSLT IN DAMAGE TO THE DRIVE BELT AND OTHER COMPONENTS AND COULD CAUSE CHARGING FAULTS.

FREE vehicle specific technical information is available by visiting <u>autoelectro.co.uk</u> OR scan this QR code



The Original and Best

Since 1986