



KNOW HOW

TECHNICAL BULLETIN



NAL1431

Bulletin Ref: TB8n

The main feed from the battery to alternator is prone to breaking, double check this is in good condition before ordering and fitting.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk