


SERVICE BULLETIN Subject: Installation of Concentric Slave Cylinder (CSC) Your undercarriage specialist

CPD Part No: OPE301P

Issue Date: March 2018 FITMENT AWARENESS FOR OPE301P

- MAKE SURE CLIP IS SECURE IN HOUSING WITH BOTH TEETH
- MAKE SURE HOUSING IS NOT RUSTED AT BACK END WHERE CLIP IS SECURED
- IF RUSTED, PUSHROD CAN BREAK THROUGH THE HOUSING AND SNAP OFF
- WELD HOUSING BEFORE FITMENT OF **CLUTCH MASTER**



be shown incorrectly.

www.capeparts.com