

CRITICAL INSTRUCTIONS

Application: **Saab 9-3/9-5 Petrol Engine**

Part Number:

452204-5005S

452204-0005E

WHEN FITTING THIS TURBO, IT IS **CRITICAL** THE FOLLOWING INSTRUCTIONS ARE ADHERED TO:

- **Replace Oil Strainer and Oil Feed Pipe**

The sump should be removed and cleaned then a new oil strainer and oil feed pipe fitted

The oil feed system to the turbocharger has a tendency to become restricted over time. Most failures of this turbocharger are caused by abrasives in the oil which collect in the system. Performing the above actions will minimise the risk of the new turbocharger being damaged.

Any questions regarding the above should be directed to the supplier of this unit before commencing any work

