



LuK Service Info

Part Nr. 500 0885 40

Manufacturer: MASSEY FERGUSON

Supersession

Art.-Nr.: 500 0885 40



TB1270

Info: 500 0885 40 replaces / ersetzt
/ remplace / sustituye a / sostituisce
500 0885 10



RepSet = See Catalogue



500 0885 10
OEM 6223 296 M1



500 0885 40
OEM 3700 527 M1

Call : +44 (0) 1432 264264
vehiclelifesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT