



TB1386

LuK Service Info

Part Nr. 333 0251 10 – 327MM TDCN 21 SPLINE

Manufacturer: MASSEY FERGUSON

Model: 4225, 4235, 4245

Art.-Nr.: 333 0251 10

333 0251 10 replaces / ersetzt /
remplace / sustituye a / sostituisce
333 0145 11



633 3184 10 = 133 0008 11 + 333 0251 10 + 500 0885 40 + 410 0020 40



333 0145 11
OEM 3772439M92



333 0251 10
OEM 7029022M1

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT