



TB1400

LuK Service Info

Part Nr. 636 3036 09 – 360MM TGFR

Manufacturer: EICHER
Model: 3125 / 3145
Art.-Nr.: 636 3036 09

New Product / Neues Produkt /
Produit Nouveau / Nuevo Producto
/ Nuovo Prodotto


Info: 636 3036 09 replaces / ersetzt / remplace / sustituye a / sostituisce 636 3036 00



636 3036 09 = 136 0213 10 + 335 0081 10



136 0213 10



335 0081 10

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT