



LuK Service Info Part Nr. 500 0587 10

Manufacturer: LANDINI
Art.-Nr.: 500 0587 10



TB1418

Info: 500 0076 11 replaces / ersetzt
/ remplace / sustituye a / sostituisce
500 0587 10

Product Improvement / Produktverbesserung / Amélioration du produit / de mejora de productos
/ miglioramento del prodotto



630 3119 09 = 130 0004 10 + 330 0009 12



500 0587 10
OE 1425227M91



500 0076 11
OE 00 1154 621 0

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT