



## LuK Service Info

# Part Nr. 228 0154 10 – 280/280MM TGU6

**Manufacturer:** LANDINI, MASSEY FERGUSON, McCORMICK

LANDINI – 50V, 55V, 5860R, 5865 EVOLUTION, 60V, 6060, 6560V, BLIZZARD  
50, 60, POWERFARM 60, 65 75, 90HC, REX 60, 60F, 65F, 65GE, 75F,  
75GE, TREKKER C55F, C60F

MASSEY FERGUSON – 353, 354, 356, 363, 364, 366

McCORMICK – C60 MAX, F60, V60, V65

**Art.-Nr.: 228 0154 10**

**Info: 628 3078 09 replaces / ersetzt  
/ remplace / sustituye a / sostituisce  
228 0154 10**



**628 3078 09 = 228 0154 10 + 328 0083 16**

**628 3078 10 = 228 0154 10 + 328 0083 16 + 500 0459 00 + 500 1107 40 + 410 0042 40**



**228 0154 10  
OE 6510 441 M91**



**628 3078 09  
OE 3671 892M91**



**411 0033 11  
Hex Bolt Set M8 x 45 x 1.25 + Conical Washer**

Call : +44 (0) 1432 264264  
vehiclelifetimesolutions.schaeffler.com

**SCHAEFFLER  
REP>XPERT**



**TB1430**