



TB1433

LuK Service Info

Part Nr. 228 0019 12 – 280/280MM TGU6

Manufacturer: EICHER,

3066, 3066S, 3066SA, 3075S, 3088S, 3088AS, 3453, 3457, 3458, 3553,
3555, 3556A, 3557A, 3558, 3655, 3656, 3657, 3658, 3660

BUFFEL 74

MAMMUT A 3422, MAMMUT II 3423, MAMMUT II EM600, MAMMUT II 74(3453)

WOTAN 3066, 3085, 3085A, 3655, 3656A

Art.-Nr.: 228 0019 12

**Info: 628 1374 09 replaces / ersetzt
/ remplace / sustituye a / sostituisce
228 0019 12**



628 1374 09 = 228 0019 12 + 328 0155 17

628 1374 10 = 228 0019 12 + 328 0155 17 + 500 0058 10 + 500 0059 10



**228 0019 12
OE 3195 433 M1**



**628 1374 09
OE 3168 918 M1**

**411 0164 11
Hex Bolt Set M8 x 50 x 1.25 +
Conical Washer**



X6

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

**SCHAEFFLER
REP>XPERT**