



LuK Service Info

Part Nr. 133 0258 10 – 330 TBFR

Manufacturer: LANDINI, McCORMICK



TB1522

Art.-Nr.: 133 0258 10

**Info: 633 3039 09 / 633 3056 09 replaces /
ersetzt / remplace / sustituye a / sostituisce
133 0258 10**

OPTIONAL / WAHLWEISE / OPTIONNEL / OPCIONAL / OPTIONAL



**633 3039 09
3559 828 M91**



**633 3056 09
3667 112 M91**

**Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com**

**SCHAEFFLER
REP>XPERT**