Service Information | Serviceinformationen



Replacement of MDB4100 with MDB2732

Mintex will harmonise references MDB4100 and MDB2732 keeping only the MDB2732 in the portfolio.

Mintex has decided to change the specification of MDB2732, so that it will also get 2 wear indicators (Ix left, Ix right) to ensure the same functionality of MDB4100.

As there are no differences in the outer dimensions there will be no difficulties during assembly and operation. By doing this harmonisation, more vehicles are covered with just one reference (MDB2732), which also provides a logistical benefit for the customer.



As usual old stock of MDB4100 can be sold before completely switching to MDB2732.