## Service Information | Serviceinformationen



## Replacement of MDB3708 by MDB3926

Mintex is now able to harmonize the references MDB3708 and MDB3926. It was proven that MDB3926 can also cover the applications of MDB3708. Therefore Mintex will replace MDB3708 by MDB3926.

The difference between them is that MDB3926 contains two different pads, one with left hand springs and one with right hand springs. There will be no difficulties during installation and operation.



As usual, existing stock of MDB3708 can be sold out without any problems.