



ALTERNATEUR BMW 1502,1600

 Remanufactured

FADAAL

Core code : 01

 3599771202753



TECHNICAL DATA

Alternator Charging Current [A]	45 A
Fiche	PLUG100
Pulleys	with belt pulley
Info complémentaire	without integrated regulator
Clamp	M8 B+
Voltage [V]	12 V

PICTURES



 Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

BMW		
1500-2002 (1962-1971) - 1600	83 ch	04.1964 > 04.1968
1500-2002 (1962-1971) - 1800	90 ch	07.1969 > 09.1971
	90 ch	08.1963 > 09.1969
1500-2002 (1962-1971) - 1800 Ti	110 ch	10.1963 > 04.1968
	131 ch	10.1963 > 04.1968
1500-2002 (1962-1971) - 2000	90 ch	01.1970 > 11.1972
	100 ch	09.1968 > 07.1972
1500-2002 (1962-1971) - 2000 Ti / Tilux	120 ch	01.1966 > 07.1972
1500-2002 (1962-1971) - 2000 Tii	131 ch	12.1969 > 07.1972
1500-2002 (1962-1971) - 1602	85 ch	04.1971 > 07.1975
1500-2002 (1962-1971) - 1600/2	85 ch	12.1967 > 12.1971
1500-2002 (1962-1971) - 1600 Ti	105 ch	09.1967 > 11.1969
1500-2002 (1962-1971) - 1802	90 ch	05.1971 > 07.1975
1500-2002 (1962-1971) - 2002	100 ch	02.1968 > 07.1975
1500-2002 (1962-1971) - 2002 Ti	120 ch	06.1968 > 04.1972
1500-2002 (1962-1971) - 2002 Tii	130 ch	04.1971 > 06.1975
1500-2002 (1962-1971) - 2002 Turbo	170 ch	01.1974 > 07.1975
1500-2002 (1962-1971) - 1600-2	86 ch	12.1967 > 10.1971
1500-2002 (1962-1971) - 2002	100 ch	05.1971 > 07.1975
1500-2002 (1962-1971) - 1600	85 ch	05.1971 > 04.1973
1500-2002 (1962-1971) - 1802	90 ch	05.1971 > 07.1975
1500-2002 (1962-1971) - 2002	100 ch	05.1971 > 07.1975
1500-2002 (1962-1971) - 2002 Tii	130 ch	01.1971 > 07.1975
1600 GT Coupe - 1.6	105 ch	10.1967 > 05.1969
2000-3.2 Coupe (E9) - C/CA	101 ch	10.1965 > 06.1970
2000-3.2 Coupe (E9) - CS	120 ch	10.1965 > 06.1970