



**ALTERNATEUR ROVER 218, 41**

 Remanufactured

FADAAL

Core code : 06

 3599771218389




## TECHNICAL DATA

|                                 |   |
|---------------------------------|---|
| Alternator Charging Current [A] | <b>70 A</b>                             |
| Fiche                           | <b>PLUG275</b>                          |
| Pulleys                         | <b>with V-ribbed belt pulley</b>        |
| Info complémentaire             | <b>with integrated regulator</b>        |
| Connector/Clamp                 | <b>with connection for speed sensor</b> |
| Number of grooves               | <b>5</b>                                |
| Clamp                           | <b>M6 B+</b>                            |
| Voltage [V]                     | <b>12 V</b>                             |

## PICTURES



 Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

| <b>LADA</b>               |       |                   |
|---------------------------|-------|-------------------|
| NIVA (2121) - 1900 Diesel | 65 ch | 01.1993 > 08.1999 |
|                           | 75 ch | 01.1999 > 12.2006 |

| <b>ROVER</b>                |       |                   |
|-----------------------------|-------|-------------------|
| 200 Hatchback (XW) - 218 TD | 88 ch | 09.1991 > 10.1995 |
| 200 Hatchback (XW) - 218 D  | 71 ch | 09.1991 > 10.1995 |
| 400 (XW) - 418 TD           | 88 ch | 09.1991 > 04.1995 |
| 400 (XW) - 418 D            | 67 ch | 09.1991 > 04.1995 |
| 400 Tourer (XW) - 1.8 TD    | 88 ch | 09.1993 > 11.1998 |