




ALTERNATEUR ROVER 820I
 Remanufactured

Core code : 08

FADAAL

 3599771218457

TECHNICAL DATA

Alternator Charging Current [A]	100 A
Fiche	PLUG604
Pulleys	with V-ribbed belt pulley
Info complémentaire	with integrated regulator
Connector/Clamp	with connection for speed sensor
Number of grooves	6
Clamp	M6 B+
Voltage [V]	12 V

PICTURES


Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

LAND ROVER		
DISCOVERY (89-98) (LJ, LG) - 2.0 16 V 4x4	135 ch	06.1989 > 10.1998
RANGE ROVER (94-02) (LP) - 4.0 4x4	185 ch	06.1998 > 03.2002

ROVER		
800 Hatchback (XS) - 820 SE/SI	120 ch	10.1986 > 12.1991
800 Hatchback (XS) - 820 SI	133 ch	10.1988 > 12.1991
800 Hatchback (XS) - 820 i/Si	140 ch	10.1988 > 12.1991
800 Hatchback (XS) - 820 I/SI	136 ch	01.1991 > 02.1999
800 Hatchback (XS) - 820 16V Turbo	180 ch	11.1991 > 02.1999
800 Hatchback (XS) - 820 Sport	197 ch	04.1994 > 03.1996
800 Hatchback (XS) - 827 Vitesse Catalytic-Conv	169 ch	10.1988 > 12.1991
800 Hatchback (XS) - 827 24V I/SI Cat	169 ch	01.1992 > 02.1999
800 Hatchback (XS) - 827 Vitesse/SLI	177 ch	10.1988 > 12.1991
800 (XS) - 820	100 ch	10.1988 > 10.1991
800 (XS) - 820e	120 ch	10.1986 > 10.1991
800 (XS) - 820 SE/SI	120 ch	10.1986 > 12.1991
800 (XS) - 820 SI	133 ch	10.1988 > 12.1991
800 (XS) - 820 16 V I/SI	140 ch	10.1986 > 10.1988
800 (XS) - 820 I/SI	136 ch	01.1992 > 02.1999
800 (XS) - 820 16V Turbo	180 ch	01.1992 > 02.1999
800 (XS) - 820 Sport	197 ch	04.1994 > 03.1996
800 (XS) - 827 SI/Sterling Catalytic-Conv	169 ch	02.1988 > 02.1999
800 (XS) - 827 SI/Sterling	177 ch	02.1988 > 12.1991
800 Coupe - 820 16V	136 ch	07.1997 > 02.1999
800 Coupe - 827 24V	169 ch	08.1992 > 02.1999