



Hyundai IX35 Ring Gear Identification

Before fitting this clutch kit to a vehicle, it is important to check that the quantity of ring gear teeth on the new flywheel is the same as the flywheel that came off the car.

Up to 05/2014 the vehicle was fitted with a 110T ring gear pictured below:



ClutchPro Clutch kit: KHD24518

From 05/2014 onwards, the vehicle was fitted with a 132T Ring Gear:



ClutchPro Clutch kit: KHD24521

Both flywheels will bolt up to the crankshaft, however fitting the wrong flywheel will result in engine starting problems and possibly damage to the starter motor.





CLUTCH AND FLYWHEEL SPECIALISTS











