




# CLUTCHTECH




## TSB-CC01/CC03

### Pull Type Bearing Fitment



### Pull Type Centralisers

When fitting new centralisers, check the slider parts of the centralisers do not bottom out in the slot in the pressure plate casting. If there is no gap between the slider & the pressure plate casting the clutch will not release.



#### LEADING BRANDS

CLUTCHPRO CLUTCHPRO  
RACING



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)