



# CLUTCHTECH



## TSB - HD03

### Release Bearing Fitment

Applies to ClutchPro kit  
KHD20003, KHD20014  
(HYUNDAI ACCENT, GETZ, 1.3/1.4/1.5/1.6L)

When fitting a clutch to Hyundai Accent 1.3 and 1.5 vehicles the roll-pin on the clutch release lever outside the bellhousing should be removed in order to allow the clutch fork to move further forward so that the release bearing can be replaced.

The roll-pin is fitted to the clutch release lever to limit the free movement of the release lever, and should be pressed out of the lever before removing the old release bearing and fitting the new release bearing.

It is not possible to pivot the clutch fork inside the bellhousing forward sufficiently to remove or replace the release bearing while the roll-pin is still in place on the release lever.

Any attempt to replace the release bearing without removing the roll-pin will result in severe release bearing mounting lug distortion caused by forcing the release bearing onto the clutch fork.

A new roll-pin should always be fitted to the release lever after the release bearing has been replaced.

#### LEADING BRANDS

CLUTCHPRO CLUTCHPRO  
ROCKWELL



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)