

TECHNICAL

BULLETIN

**TECH
MATE**

Bulletin Ref: TB23a

Renault Broken Wire

AAL1163

Poor or broken connections are common on these Renault models.

Trace the main feed from the plug to the wiring loom and check for broken wires or connections.

**TECH
MATE**

For further information on this or any other issue contact the
Apec technical team by phone or email at:
Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US
#TechMate | @TechMateAuto