

Mercedes Sprinter

This vehicle could have an option of several different units fitted.

This unit replaces the following original part numbers TG17C061, TG17C041.

Please double check before ordering and fitting to the vehicle.



AAL1584





For further information on this or any other issue contact the Apec technical team by phone or email at: Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US #TechMate | @TechMateAuto