

TECHNICAL

BULLETIN



Bulletin Ref: TB10a

ASM1141

This unit should only be fitted to a vehicle with manual transmission.

Fitting this to a vehicle with automatic transmission will invalidate the warranty and may result in damage to the vehicle.

