

# TECHNICAL

# BULLETIN

**TECH  
MATE**


## APEC STARTER MOTOR ASM1521

Apec Starter Motor ASM1521 may look slightly different to the unit that is currently on the vehicle. This discrepancy, while noticeable, is within standard specifications and does not warrant concern.

ASM1521 features a 12-tooth pinion drive, whereas the existing unit on the vehicle may have a 10-tooth pinion drive. It is important to understand that these units are fully interchangeable and will not impact the vehicle's performance in any way.

### APPLICATIONS AFFECTED:

- Ford B-Max, 2012 – 2018
- Ford EcoSport, 2013 – 2024
- Ford Fiesta, 2002 – 2018
- Ford Fusion, 2002 – 2012
- Ford Transit, 2014 – 2024
- Mazda 2, 2003 – 2015

### OE NUMBERS AFFECTED:

- 1483817, 1670812, 1680223, 1734633, 1762873, 1858879, Y401-18-400



### TECHNICAL DATA

Voltage	12V
Starter Output	1.4kW
Rotation Direction	Clockwise rotation
Number of Teeth	12
Number of Threaded Holes	2
Number of Mounting Bores	3

**TECH  
MATE**

For further information on this or any other issue contact the  
Apec technical team by phone or email at:  
Phone: 01174 288090 Email: [technical@apecautomotive.co.uk](mailto:technical@apecautomotive.co.uk)



**FOLLOW US**  
#TechMate | @TechMateAuto