

# TECHNICAL

# BULLETIN

**TECH  
MATE**

Bulletin Ref: TB26a

## Start Stop Warning

**ASM1565**

This unit should only be fitted to a vehicle without start stop function.

Fitting this to a vehicle with start stop function will invalidate the warranty and may result in damage to the vehicle.

**TECH  
MATE**

For further information on this or any other issue contact the  
Apec technical team by phone or email at:  
Phone: 01174 288090 Email: [technical@apecautomotive.co.uk](mailto:technical@apecautomotive.co.uk)



**FOLLOW US**  
#TechMate | @TechMateAuto