

Important technical note relating to this unit

This vehicle has a computer driven excitation circuit of the alternator regulator which takes data from the ambient temperature and engine load, a failed temperature sensor or broken wire to the regulator will result in a low charge voltage

Please double check before ordering and fitting.