

Important technical note relating to this unit

This vehicle is prone to an intermittent issue which can trigger a charging error pointing to the alternator.

Often disconnecting the battery for up to 2 hours will clear the ECU fault.