Important technical note relating to this unit

Vehicles equipped with stop/start system were subject to a main dealer recall in 2017

'A risk of fire while driving due to thermal damage of the starter cable'

It is vital that this is checked and replaced if the starter motor connection has melted.

