

Important technical note relating to this unit

This vehicle is prone to the ignition start button failing, remaining in the start position causing the starter motor to continually run, this will result in the starter motor premature burning out and also a risk of fire due to overheating.

Please double check the switch before ordering and fitting