

Important technical note relating to this unit

A charging issue on the Mercedes A Class CDi is often due to a fault with the ECU or 'SAM' control unit.

Both of these control units control and monitor the alternator charge output.