

Important technical note relating to this unit

Poor or broken connections are common on these Renault models.

Trace the main feed from the plug to the wiring loom and check for broken wires or connections.