

Product info sheet


Robert Bosch

0445010009

Special tools needed?

Yes

Pulling out and fixing the pump drivewheel



Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

primepump activated 30 sec at ignition on

adjustment at mounting_1

No

adjustment at mounting_2

--

Tightening torques

Mounting fuelpump flange

23 Nm

Pump pulley/sprocket

65 Nm

Cover / dustcap

30 Nm

High Pressure pipe nuts

23 Nm

Inlet manifold

M6: 10 Nm, M7: 15 Nm, M8: 22 Nm

Assembly instructions

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.