

Product info sh	neet	Robert Bosch	0445110520
Special tools needed?	No		
Product specific information			
Programming	Yes	IMA code (8 characters)	860 95310 1731
			1602
Unlocking	No		<i>P</i> = <i>Q</i> =
Adaption values reset	No		56 BA 6N 580
Bleed	No		
adjustment at mounting_1	No		
adjustment at mounting 2			
adjustment at mounting_2			
		Tightening torques	
Injector/ retainingclamp		28 Nm	
High Pressure pipe nuts		25 Nm	
		Assembly instruction	ns
Replace sealing washer			
Recommendation: replace fuel filter			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled,			
-no heavy corrosion.			