

IMPORTANT THIS PART HAS KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

THIS ALTERNATOR FAILS PREMATURELY DUE TO AN EXTERNAL VEHICLE FAULT.

THE COMMON FAILURE EXHIBITS RAPID OXIDAIZATION OF THE COMPONENTS DUE TO WATER INGRESS CAUSING RUST

This part is covered under a return to supplier Warranty,

and must be returned back to the manufacturer for assessment in the event of premature failure. If the manufacturer is satisfied the claim is a genuine warranty and failure has occurred due to a manufacturing defect only then will a Credit be raised. Under no circumstances will this part be accepted for credit if fitted.

Your statutory rights are unaffected.

FREE vehicle specific technical information is available by visiting <u>autoelectro.co.uk</u> OR scan this QR code



The Original and Best

Since 1986