

40-1388FK vs 40-1345FK

! IJS GROUP products should be replaced by a qualified automotive installer. This information is provided for reference purposes only. Always consult the manufacturer's specifications.

IJS GROUP supplies two kits for the Mitsubishi 4M41 engine. The two kits differ based on the position of the hole in the timing gear, with one kit designed for the hole at the top and the other for the hole at the bottom, ensuring correct installation.

DIFFERENCE

40-1345FK



40-1388FK



TIMING GEAR



OEM SPECIFICATION

- ME195055 → TIMIN GEAR

- 1132A012 → TIMIN GEAR