


MDB2846 / MDB3365 → WVAs 24468 / 24469

For the reference MDB2846 Fiat have changed their corresponding OES reference from one wear indicator to two wear indicators per set. Not used wear indicators have to be simply cut off during assembly.

In order to be in line with the OES programme we will do the same change. As a result of this we will replace MDB2846 by MDB3365.




Existing stock of MDB2846 can be sold out. Please take care that only vehicles equipped with one wear indicator can use MDB2846.

MDB2846 / MDB3365 → WVAs 24468 / 24469

Für den Artikel MDB2846 hat Fiat den entsprechenden OES Artikel von einem auf zwei Verschleißanzeiger pro Belagsatz umgestellt. Nicht benötigte Verschleißanzeiger können während der Montage einfach abgeschnitten werden.

Mintex wird diese Änderung auch für die eigenen Produkte übernehmen. Als Resultat daraus wird MDB2846 durch MDB3365 ersetzt.



Noch existierender Bestand von MDB2846 kann verkauft werden. Bitte achten Sie während der Montage darauf, dass nur Fahrzeuge mit einem Verschleißanzeiger den Artikel MDB2846 nutzen können.