

PUMP EXPERTISE

MECHANICAL WATER PUMPS – FOR A LONG ENGINE LIFE

Mechanical water pumps are responsible for transporting coolant in the engine cooling system. They have long been the component that protects engines from overheating and associated damage. Pierburg produces over 7 million mechanical water pumps as original equipment each year. The pumps are characterised by high-quality components.

Quality features of our water pumps:

- High-quality sliding ring sealing cartridge
- Maintenance-free, long-life rolling bearings
- Flow-optimised impellers made from plastic, steel, aluminium or brass
- Gaskets and O-rings are included in the scope of supply

The cooling liquid of the water pump absorbs the heat from the engine block and cylinder head and releases it into the ambient air through the cooler. Depending on their design, mechanical water pumps are located either externally on the engine in their own pump housing or are flanged directly on the crankcase and are driven by a V-belt, toothed belt or the engine directly.



Technical information:

- Models
- Fitting instructions
- Running-in notes

are available at:

www.ms-motorservice.com/pumps

PUMP EXPERTISE

Pierburg No.	Manufacturer	Ref. No. *
7.02543.05.0	Citroën Ford Mazda Peugeot Suzuki Toyota	1609313780; 1609417380; 1609418280; 1201 F9; 1201 G8; 1147585; 1348621; 1359942; 1366614; 1420149; 1705390; 2S6Q8501AA; 2S6Q8591BA; 2SQ68591BA; ME2S6Q8591B1A; Y401-15-010; Y401-15-010A; 17400-73J00; SU001-00596
7.03738.03.0	Citroën Fiat Ford Mazda Mini (BMW) Opel Peugeot Suzuki Vauxhall Volvo	1609314080; 1609417680; 609418480; 9654514780; 9686680780; 1201 G1; 1201 G9; 201 K8; 9654514780; 16 094; 176 80; 1232179; 1313842; 1351130; 1364681; 1430428; 1715839; 3M5Q8591BB; 3M5Q8591CA; ME3M5Q8591C2A; Y601-15-010; Y601-15-010A; Y601-15-010B; Y601-15-S20; 1151 7 805 992; 3646435; 17400-69K00; 3646435; 30711527; 30751971
7.06395.06.0	Dacia Mercedes-Benz Nissan Renault	21 01 093 34R; 282 200 06 00; A 282 200 06 00; 11060-00Q2B; 21 01 093 34R
7.07152.05.0	Audi Seat Škoda Volkswagen	03L 121 011; 03L 121 011 C; 03L 121 011 H; 03L 121 011 HX; 03L 121 011 J; 03L 121 011 JX; 03L 121 011 P; 03L 121 011 PX; 03L 121 011 V; 03L 121 011 X
7.07152.11.0	Audi Ford Seat Škoda Volkswagen	045 121 011 F; 045 121 011 FV; 045 121 011 FX; 045 121 011 H; 045 121 011 HV; 045 121 011 HX; 1101228; 1124940; 1138725; 1250684; 1250685; 1459215; 1459216; 1673517; 3M21 8501 AA; 6M21 8501 AA; ME6M218501A1A; RM3M218501AA; RM6M218501AA
7.07152.17.0	Ford Mazda Volvo	1007714; 1020538; 1077539; 1132607; 1326374; 1350460; 1350461; 1566239; 96MX 8591 AA; 98MM 8501 BC; C201-15-010A; EPW80; MEYS6G8591A1D; YS6G8501A2C; YS6G8591A2C; 1E05-15-010; C201-15-010; C202-15-010A; 30735758; 31401653; 31493369
7.29611.06.0	Dacia Mercedes-Benz Nissan Renault	21 01 061 13R; 21 01 074 77R; 77 01 478 830; 82 00 713 853; WP3620101; 607 200 00 07; A 607 200 00 07; A 608 200 10 00; 21010-00Q0M; 1010-00Q3L;

All content including pictures and diagrams is subject to change. For assignment and replacement, refer to the current catalogues or systems based on TecAlliance.

OUR **HEART** BEATS FOR YOUR ENGINE.