



OIL PUMP REPAIR KIT PTA420-3010 and PTA420-3011

Technical information for installation

Attention!

The oil pump kits PTA420-3010 and PTA420-3011 contain **two similar chain tensioners** for the oil pump drive.

Compare the removed chain tensioner with the two supplied and **use only the appropriate chain tensioner.**

