



# Camshaft phasing units for BMW engines e.g. B38, B42, B48, B58

## General information

### Please note!

- When replacing the intake and exhaust camshaft phasers, pay attention to the part number (reference number)!
- Only one inlet and outlet adjustment unit with consecutive part number [PTA126-0207 + PTA126-0208] may be installed at any one time. This means that the camshaft phasers must be replaced in pairs according to the diagram below!
- Assembly of non-paired parts is not permitted!

### Note:

The manufacturer-specific repair instructions and special tools must be observed and used for all work.

After replacing the intake and exhaust camshaft phasing units, the “I stage” service function must be programmed and, if necessary, coded using the appropriate diagnostic unit.

Intake camshaft phasing units

#### PTA126-0207

Reference number:  
11 36 8 684 920



#### PTA126-0249

Reference number:  
11 36 7 608 788



#### PTA126-0251

Reference number:  
11 36 8 617 692



+

+

+

Exhaust camshaft phasing units

#### PTA126-0208

Reference number:  
11 36 8 684 921



#### PTA126-0250

Reference number:  
11 36 7 608 789



#### PTA126-0252

Reference number:  
11 36 8 617 693



In the event of a warranty claim, proof of programming or coding must be enclosed.