


NAL1163 - Renault Broken Wire

Bulletin Ref: TB23n

Poor or broken connections are common on these Renault models. Trace the main feed from the plug to the wiring loom and check for broken wires or connections.



Technical Support

Contact our expert technical team on 03333 136597 or email NAPAtechnical@allianceautomotive.co.uk



TECH TechMate Support

Book a TechMate visit today! Contact the team on 01174 288090 or email info@techmateteam.co.uk