



KNOW HOW

TECHNICAL BULLETIN





NAL1584 - Mercedes Sprinter

Bulletin Ref: TB25n

This vehicle could have an option of several different units fitted.

This unit replaces the following original part numbers TG17C061, TG17C041.

Please double check before ordering and fitting to the vehicle.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk