



KNOW HOW




TECHNICAL BULLETIN



NAL1598 - Renault Broken Wire

Bulletin Ref: TB23n

Poor or broken connections are common on these Renault models.
Trace the main feed from the plug to the wiring loom and check for broken wires or connections.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk

**TECH
MATE**

TECHNICAL
PARTNER

TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk