


NSM1701

Bulletin Ref: TB26n

This unit should only be fitted to a vehicle without start stop function. Fitting this to a vehicle with start stop function will invalidate the warranty and may result in damage to the vehicle.



Technical Support

Contact our expert technical team on 03333 136597 or email NAPAtechnical@allianceautomotive.co.uk



TECH TechMate Support

Book a TechMate visit today! Contact the team on 01174 288090 or email info@techmateteam.co.uk