

ISU2123- CSC 22.22MM ISUZU KB250/ KB300 2004-2013

FITMENT INSTRUCTIONS FOR ISU2123

PLEASE NOTE: NO CREDITS WILL BE ENTERTAINED FOR INCORRECT FITMENT AND BLEEDING.

- I) Replace electronic switch from old cylinder to new
- Conventional bleeding of your clutch will not work due to the feed pipe and nipple being so close.
- 3) Reverse bleeding is required; therefore a reverse bleeder is mandatory.
- Ensure clutch pedal height and master cylinder pushrod free play measurements are correctas per manufacturers' specifications.
- 5) Reverse bleed following the instructions that came with the reverse bleeder until you are satisfied with the pedal feel.
 (1) Ensure the brace fluid level is connect.

.

6) Ensure the brake fluid level is correct.

FOR FURTHER ASSISTANCE ON HOW TO BLEED THE CLUTCH SLAVE SEE THE QR CODE AND/OR LINK BELOW:

https://www.youtube.com/watch?v=epSwRE49Hoc



the second second

 sales@capeparts.com
 www.capeparts.com
 041 487 1471
 081 357 5794 ANDREW · SAM · DYLAN · WESLEY