


# STEER.



## EC3028 & EC3928 ELECTRIC STEERING COLUMN IDENTIFICATION Opel / Vauxhall Corsa C with adjustable column

Care should be taken when identifying the correct Steering Column depending on the Fault Codes.


### EC3028

supplied with ECU  
required when the fault code is -  
C1507 or C1509 - Motor Voltage Fault



### EC3928

supplied without ECU  
required when the fault code is -  
C1500 - Torque Sensor Fault



STEC.10048 18/08/23

