









Product info sheet		Robert Bosch	0445110141	
Special tools needed?	No			
	Pro	oduct specific informa	ation	
Programming	No			
Unlocking	No			
Adaption values reset	No			
Bleed	No			
adjustment at mounting_	1			
adjustment at mounting_	_2			
	1, 11			
		Tightening torques		
Injector/ retainingclamp		1: Nuts both sides	1: Nuts both sides: 6 Nm 2: Flywheelside: +360°	
High Pressure pipe nuts		1: rail 22 Nm 2: inj	jector 25 Nm 3: rail 27 Nm	
			A	
		Assembly instruction	ıs	
Replace bolts/studs and r	nuts	•		
Replace sealing washer				
. •				
Core charge terms:				
-externally intact,-no mechanical damage				
-not dismantled,	,			
-no heavy corrosion.				