

Product info sheet

Robert Bosch

0445110279

Special tools needed?

No

Product specific information

Programming

Yes

Classification code

The codes (C1, C2, C3) must be the same for each cylinder, unless the diagnostic tool can program each cylinder specific. Only then mixed mounting is allowed.

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting_1

--

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

33 Nm

High Pressure pipe nuts

28 Nm

Assembly instructions

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

